

EXPEDITED SPCC SETTLEMENT AGREEMENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 7, 901 N. 5th ST., KANSAS CITY, KANSAS 66101

03 SEP 12 AM 9:21

Facility Name: Western Engineering Co., Inc.

Location: N. Platte Yard, 3201 E. Hwy 30, North Platte, NE 69101

Owner/Operator: Evert Falkena

(Respondent)

On August 2, 2002, an authorized representative of the United States Environmental Protection Agency (EPA) conducted an inspection to determine compliance with the Oil Pollution Prevention (SPCC) regulations promulgated at 40 CFR Part 112 under Section 311(j) of the Clean Water Act (33 U.S.C. § 1321(j)) (the Act), and found that Respondent had violated regulations implementing Section 311(j) of the Act by failing to comply with the regulations as 311(j) of the Act by failing to comply with the regulations as noted on the attached Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form (Form), which is hereby incorporated by reference.

If Respondent does not sign and return this Expedited Settlement as presented within 30 days of the date of its receipt, the proposed Expedited Settlement is withdrawn without prejudice to EPA's ability to file any other enforcement action for the violations identified in the Form.

This proceeding and the Expedited Settlement are under the authority vested in the Administrator of EPA by Section authority vested in the Administrator of EPA by Section 311(b) (6) (B) (i) of the Act, 33 U.S.C. § 1321(b) (6) (B) (i), as amended by the Oil Pollution Act of 1990, and 40 CFR §§ 22.13(b) and 22.18(b), published at 64 Fed. Reg. 40137 on July 23, 1999. The parties enter into this Expedited Settlement in order to settle the civil violations described in the Form for a penalty of \$2500.00. This settlement is subject to the following terms and conditions:

EPA finds that Respondent is subject to the SPCC regulations, which are published at 40 CFR Part 112, and has regulations, which are published at 40 CFR Part 112, and has violated the regulations as further described in the Form. Respondent admits that he/she is subject to 40 CFR Part 112 and that EPA has jurisdiction over Respondent and Respondent's conduct as described in the Form. Respondent does not contest the Inspection Findings, and waives any objections it may have to EPA's jurisdiction. Respondent consents to the assessment of the penalty stated above.

Respondent certifies, subject to civil and criminal penalties for making a false submission to the United States Government, that the violations have been corrected and Respondent has sent a certified check in the amount of \$2500.00 payable to the "Oil Spill Liability Trust Fund," to:

"Regional Hearing Clerk, Office of Regional Counsel, U.S. Environmental Protection Agency, 901 N. 5th Street, Kansas City, Kansas 66101". Respondent has noted on the penalty payment check "CWA-07-2003-0211" the docket number of this case.

(Do Not Make Check Out to the Regional Hearing Clerk)

DOCKET NO: CWA-0712003H02111L PROTECTION AGENCY-REGION VII

This Expedited Settlemen REGSON ART RESIDENCE SIAbility for Federal civil penalties for the violations of the SPCC regulations described in the Form. However, EPA does not waive any rights to take any enforcement action for any other past, present, or future violations by Respondent of the SPCC regulations or of any other federal statute or regulations. By its first signature, EPA ratifies the Inspection Findings and Alleged Violations set forth in the Form.

Upon signing and returning this Expedited Settlement to EPA, Respondent waives the opportunity for a hearing or appeal pursuant to Section 311 of the Act, and consents to EPA's approval of the Expedited Settlement without further notice.

This Expedited Settlement is binding on the parties signing below, and is effective upon the Regional Judicial Officer's signature.

Chief, Emergency Planning & Response Branch, Superfund, Division

APPROVED BY RESPONDENT:

Name (print): CARL EPLEY

MANIA COR Title (print): Contract

Robert L. Patrick

Regional Judicial Officer

INSTRUCTIONS ON REVERSE

Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form

(Note: Do not use this form if there is no secondary containment)

These Findings, Alleged Violations and Penalties are issued by EPA Region 7 under the authority vested in the Administrator of EPA by Section 311(b)(6)(B)(i) of the Clean Water Act, as amended by the Oil Pollution Act of 1990

Co	mpany Name	Docket Number: CWA
W	stern Engineering Co., Inc	7 - 2 0 0 3 - 0 2 1 1 B A A A A A A A A A A A A A A A A A
Fac	ility Name	Date
No	rth Platte Yard	8/2/02
Ad	dres <i>s</i>	Inspection Number
320	0) E. Hwy 30	F Y - I N S P - 0 2 - 0
Cit	у:	Inspector's Name:
No	rth Platte	Marc Callaghan
Sta	te: Zip Code:	EPA Approving Official:
NE	69101	Bob Jackson
Fac	city Contact:	Enforcement Contacts:
Ev	ert Falkena	Bob Webber Phone Number: (913)551-7251 Alan Hancock Phone Number: (913)551-7647
(Bulk Storage Facilities) GENERAL TOPICS: 112.3(d), (e); 112.5(a), (b), (c); 112.7 (b), (c), (d) (When the SPCC Plan review penalty exceeds \$1,000.00 enter only the maximum allowable of \$1,000.00.)		
	No Spill Prevention Control and Countermea	sure Plan \$1,000.00
	Plan not certified by a professional engineer	
X	No management approval of plan	
	Plan not available for review	
	Plan not maintained on site (applies if facility	y is manned at least eight (8) hours per day) 100.00
	No evidence of three-year review of plan by	owner/operator
	No plan amendment(s) if the facility has had or maintenance which affects the facility's di	a change in: design, construction, operation, scharge potential
	Amendment(s) not certified by a professional	l engineer100.00
	Inadequate or no prediction of equipment fail	lure which could result in discharges 100.00
		nt/diversionary structures/equipment

When drainage from diked areas is to a storm drain, open water course, or lake or pond:		
	Bypass valve not normally sealed closed	
	Runoff rain water not inspected and/or will cause a harmful discharge as defined in 40 CFR 110 300.00	
	Bypass valve is not opened and resealed under responsible supervision	
	Adequate records of drainage events are not maintained	
	Underground tanks are not protected from corrosion or are not subjected to regular pressure testing 100.00	
	Partially buried tanks do not have buried sections protected from corrosion	
\overline{X}	Aboveground tanks not subject to periodic integrity testing, such as visual, hydrostatic, and nondestructive methods, etc	
	Outside of tank not frequently observed for signs of deterioration, leaks which might cause a spill, or accumulation of oil inside diked area	
	Steam return /exhaust of internal heating coils which discharge into an open water course not monitored, passed through a settling tank, skimmer, or other separation system	
	Records of inspections of aboveground tanks are not maintained	
	Tanks are not "fail-safe" engineered:	
	No audible or visual high liquid level alarm, or	
	No high-level pump cutoff devices set to stop flow at a predetermined tank content level, or 300.00	
	No direct communications between tank gauger and pumping station, or	
	No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges	
	No testing of liquid level sensing devices to ensure proper operation	
	Disposal facilities which discharge plant effluents directly to navigable waters are not monitored frequently to detect oil spills	
	Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300.00	
	Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding	
	Secondary containment inadequate for mobile or portable storage tanks	
	Plan has inadequate or no discussion of bulk storage tanks 50.00	
FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE (excluding Production Facilities) 112.7(e)(3)		
	Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection 100.00	
	Corrective action not taken on buried piping when corrosion damage found	
	Terminal connections at transfer points on not-in-service or standby pipelines are not capped or blank-flanged and marked as to origin	

IN THE MATTER OF Western Engineering Co., Inc., Respondent Docket No. CWA-07-2003-0211

CERTIFICATE OF SERVICE

I certify that the foregoing Expedited SPCC Settlement Agreement was sent this day in the following manner to the addressees:

Copy hand delivered to Attorney for Complainant:

Kristina Kemp Assistant Regional Counsel Region VII United States Environmental Protection Agency 901 N. 5th Street Kansas City, Kansas 66101

Copy by Certified Mail Return Receipt to:

Evert Falkena Western Engineering Co., Inc. 3201 E. HWY 30 North Platte, Nebraska 69101

Copy by First Class Mail to:

US. Coast Guard Finance Center (OGR) 1430A Kristina Way Chesapeake, VA 23326

Dated: 15/05

Kathy Robinson

Regional Hearing Clerk